

MOTORSPORTS INSPECTION REPORT

MAKE: 2015 BMW VIN: 408269
 MODEL: S 1000R ODO: 44 949 kms

GOOD	OK	FAIL	ENGINE / TRANSMISSION
------	----	------	-----------------------

α			IGNITION
α			THROTTLE
α			TEMPERATURE
α	α		AIR FILTER
α			DRIVE BELT / CHAIN
α			FUEL SYSTEM / LINES
α			SPARK PLUGS
α			STEERING SYSTEM
α			EXHAUST SYSTEM
α			FORWARD GEAR
α			REVERSE GEAR
α			NEUTRAL / IDLE
α			SEALS / GASKETS

NOTES:

ign good
 Throttle freeply good
 temp good
 air filter OK
 chain/sprockets good
 starts/runs
 good shift

GOOD	OK	FAIL	ELECTRONICS
------	----	------	-------------

α			HEAD LIGHT
α			TAIL LIGHT
α			BRAKE LIGHT
α			HAZARDS
α			BATTERY
α			INSTRUMENT PANEL
α			WIRING / SWITCHES

NOTES:

lights good
 wiring good
 switches good
 battery good (has tender)

GOOD	OK	FAIL	BRAKES
------	----	------	--------

α			FRONT BRAKES
α			REAR BRAKES
α			EMERGENCY BRAKE
α			BRAKE MASTER CYLINDER
α			BRAKE HOSES / LINES
α			BRAKE LEVERS

NOTES:

ft brakes 70% left
 rear brakes 90% left
 no damages

GOOD	OK	FAIL	BODY / WHEELS & TIRES
------	----	------	-----------------------

α			TIRE WEAR / PSI
α			LUGS TORQUED
α			WHEEL BEARINGS
α			BOOT JOINTS
α			SUSPENSION
α			FRAME / CHASSIS
α			PLASTICS / COSMETIC

NOTES:

tires good
 brgs good
 susp good
 clean unit

GOOD	OK	FAIL	FLUIDS
------	----	------	--------

α			MOTOR OIL
α			TRANSMISSION OIL
α			DIFFERENTIAL OIL
α			BRAKE FLUIDS
α			COOLANT / RADIATOR

NOTES:

oil good
 brake fluids good
 coolant good
 no leaks

INSPECTED BY (PRINT): UNLEASHED CYCLE AND SLED

DATE COMPLETED: June 12/24

INSPECTED BY (SIGNED): 

SERVICE CONTACT #: (587) 338-8358