

MOTORSPORTS INSPECTION REPORT

MAKE: 2006 Suzuki VIN: 102914
 MODEL: Backward VL1500 ODO: 26154 kms

GOOD	OK	FAIL	ENGINE / TRANSMISSION
------	----	------	-----------------------

✓			IGNITION
✓			THROTTLE
✓			TEMPERATURE
✓			AIR FILTER
✓			DRIVE BELT / CHAIN
✓			FUEL SYSTEM / LINES
✓			SPARK PLUGS
✓			STEERING SYSTEM
✓			EXHAUST SYSTEM
✓			FORWARD GEAR
✓			REVERSE GEAR
✓			NEUTRAL / IDLE
✓			SEALS / GASKETS

NOTES:

ign good
 good throttle play
 air filter ok
 fuel system good
 starts/runs
 good shift
 no leaks

GOOD	OK	FAIL	ELECTRONICS
------	----	------	-------------

✓			HEAD LIGHT
✓			TAIL LIGHT
✓			BRAKE LIGHT
✓			HAZARDS
✓			BATTERY
✓			INSTRUMENT PANEL
✓			WIRING / SWITCHES

NOTES:

lights good
 wiring good
 switches good
 battery good

GOOD	OK	FAIL	BRAKES
------	----	------	--------

✓			FRONT BRAKES
✓			REAR BRAKES
✓			EMERGENCY BRAKE
✓			BRAKE MASTER CYLINDER
✓			BRAKE HOSES / LINES
✓			BRAKE LEVERS

NOTES:

ft brakes 85%
 rear brakes 85%
 no damage

GOOD	OK	FAIL	BODY / WHEELS & TIRES
------	----	------	-----------------------

✓			TIRE WEAR / PSI
✓			LUGS TORQUED
✓			WHEEL BEARINGS
✓			BOB JOINTS
✓			SUSPENSION
✓	✓		FRAME / CHASSIS
			PLASTICS / COSMETIC

NOTES:

tires good
 bgs good
 susp good
 minor scuff

GOOD	OK	FAIL	FLUIDS
------	----	------	--------

✓			MOTOR OIL
✓			TRANSMISSION OIL
✓			DIFFERENTIAL OIL
✓			BRAKE FLUIDS
✓			COOLANT / RADIATOR

NOTES:

oil good
 dif oil good
 brake fluids good
 coolant good

INSPECTED BY (PRINT): UNLEASHED CYCLE AND SLED

DATE COMPLETED: Sept 9/24

INSPECTED BY (SIGNED): 

SERVICE CONTACT #: (587) 338-8358